



Asbestos Six-Month Periodic Surveillance

-- Building Materials Installed at Time of Initial Inspection

Peotone Elem. School
 426 N. Conrad Street
 Peotone, IL 60468
 School ID#: 56-099-207U-2003
 Peotone C.U.S.D. 207U

RECEIVED
 MAY 27 2015

Surveillance Date: 4/8/2015
 Ideal Job Number: 18744

Mr. Gary Love, Maintenance Director
 Phone Number: 708-258-0991

BY: _____

Initial inspection of the building section(s) noted on this report has been conducted. Known & assumed asbestos containing materials installed at the time of initial inspection are noted below. This report also includes any subsequently installed materials that have been sampled & found to be asbestos containing or have been assumed to contain asbestos.

Area ID	Area Description	Area Location	Sampled & Analysis Type or Assumed	Material Type	Damage Condition	Friable	Response Action #	Change in Condition		See Notes
								Yes	No	
01	Cement Corners on Fiberglass Lines	1959 Original Building Boiler Room, Throughout Building	Sampled PLM	T	ND	Yes	6		X	
01 (tunnels)	Cement Corners on Fiberglass Lines	1959 Original Building/1969/1971 Addition Tunnels (access restricted: metal floor panels in classrooms, boiler room locked)	Sampled PLM	T	ND	Yes	7		X	1
02	Insulation on Breaching	1959 Original Building Boiler Room	Sampled PLM	T	ND	Yes	7		X	
03	Transite Panels	1959 Original Building Classrooms Behind Bookcases	Sampled PLM	M	ND	No	N/A		X	
04	Transite Panels	1959 Original Building Hallway Above Lockers	Sampled PLM	M	ND	No	N/A		X	
05	9x9 Grey Floor Tile	1959 Original Building Rooms 116, 118 & 120, Stage, Gym & Coach's Room (some removed from stage)	Sampled PLM	M	ND	No	N/A		X	2
06	9x9 Brown Floor Tile	1959 Original Building Room 109, 113, 117, 119, 122-126, Kitchen Storage, Teachers' Restroom, Stage Hall (two layers-some removed)	Sampled PLM	M	ND	No	N/A		X	2, 5
07	9x9 Dark Brown Floor Tile	1959 Original Building Office Area & Rooms 111 & 114 (some removed)	Sampled PLM	M	ND	No	N/A		X	2

Surveyor: Steve Rock
 Surveyor #: 100-05617

Notes: 1) Accessed in limited area. It is assumed that no changes have taken place. 2) Area location has been updated. 3) Covered with linoleum. 4) Assumed to contain asbestos 4/8/2015. 5) Removed from kitchen storage 8/2014.

Areas removed & reported as such on prior reports are not listed on this report. Prior to any renovation/demolition, a specific inspection for localized and/or hidden suspect asbestos areas must be done, & this report is not a substitute for such an inspection. This report reflects information from the most current 3-year asbestos reinspection & subsequent 6-month surveillance reports. Changes in condition reflect observed changes since the last report only, not repairs and/or localized removal that may have been done previously. For changes in condition, "no" shall mean "none apparent". "Accessible" indicates materials, spaces or areas for which nothing is required to be removed to access the material, space, or area (i.e. no walls, ceilings, floors, outlet covers, etc. are required to be removed). "Inaccessible" indicates materials, spaces or areas for which something is required to be removed to access the material, space, or area. IDEAL reserves the right not to enter tunnels, crawlspaces, pipe chases or other area due to limited accessibility and/or confined space concerns. Recommendations and/or remediation instructions are not a required part of this service. While some may be provided, they may not be detailed to cover all affected regulations & shall not be interpreted as such. Materials installed since the initial AHERA inspection may not be identified on this report. The materials are to be treated as suspect asbestos containing materials, & all applicable asbestos regulations are to be followed regarding these materials, regardless of installation date.

ACM = Asbestos Containing Material Non-ACM = Non-Asbestos Containing Material
 Damage Condition: ND=Not Damaged; D=Damaged; SD=Significantly Damaged Material Type: M=Miscellaneous; S=Surfacing; T=Thermal
 PLM = Polarized Light Microscopy TEM = Transmission Electron Microscopy N/A = Not Applicable



Asbestos Six-Month Periodic Surveillance

-- Building Materials Installed at Time of Initial Inspection

Peotone Elem. School
 426 N. Conrad Street
 Peotone, IL 60468
 School ID#: 56-099-207U-2003
 Peotone C.U.S.D. 207U

Surveillance Date: 4/8/2015
 Ideal Job Number: 18744

Mr. Gary Love, Maintenance Director
 Phone Number: 708-258-0991

Initial inspection of the building section(s) noted on this report has been conducted. Known & assumed asbestos containing materials installed at the time of initial inspection are noted below. This report also includes any subsequently installed materials that have been sampled & found to be asbestos containing or have been assumed to contain asbestos.

Area ID	Area Description	Area Location	Sampled & Analysis Type or Assumed	Material Type	Damage Condition	Friable	Response Action #	Change in Condition		See Notes
								Yes	No	
08	9x9 Grey/Black Floor Tile	1959 Original Building Restroom (some replaced)	Sampled PLM	M	ND	No	N/A		X	2,3
08MMA	9x9 Floor Tile Mastic	1959 Original Building Various Areas Throughout (some removed)	Sampled PLM	M	ND	No	N/A		X	
08MMB	12x12 Floor Tile Mastic	1969 West Wing Addition Classrooms (some removed)	Sampled PLM	M	ND	No	N/A		X	2
09	9x9 Grey w/Pink Floor Tile	1959 Original Building Rooms 106 & 108	Sampled PLM	M	ND	No	N/A		X	2
10	12x12 White w/Grey Floor Tile	1969 Addition Kindergarten Wing Rooms 101-105 (some covered over) (some removed)	Sampled PLM	M	ND	No	N/A		X	2
11	9x9 Tan w/Pink & Green Floor Tile	1959 Original Building Rooms 122, 124 & 126	Sampled PLM	M	ND	No	N/A		X	2
12	12x12 Grey w/Streaks Floor Tile	1959 Original Building Restroom (covered with vinyl flooring)	Sampled PLM	M	ND	No	N/A		X	2
13	12x12 Grey Streaked Floor Tile	1969 Addition Restrooms (covered with vinyl flooring)	Sampled PLM	M	ND	No	N/A		X	2

Surveyor: Steve Rock

Surveyor #: 100-05617

Notes: 1) Accessed in limited area. It is assumed that no changes have taken place. 2) Area location has been updated. 3) Covered with linoleum. 4) Assumed to contain asbestos 4/8/2015. 5) Removed from kitchen storage 8/2014.

Areas removed & reported as such on prior reports are not listed on this report. Prior to any renovation/demolition, a specific inspection for localized and/or hidden suspect asbestos areas must be done, & this report is not a substitute for such an inspection. This report reflects information from the most current 3-year asbestos reinspection & subsequent 6-month surveillance reports. Changes in condition reflect observed changes since the last report only, not repairs and/or localized removal that may have been done previously. For changes in condition, "no" shall mean "none apparent". "Accessible" indicates materials, spaces or areas for which nothing is required to be removed to access the material, space, or area (i.e. no walls, ceilings, floors, outlet covers, etc. are required to be removed). "Inaccessible" indicates materials, spaces or areas for which something is required to be removed to access the material, space, or area. IDEAL reserves the right not to enter tunnels, crawlspaces, pipe chases or other area due to limited accessibility and/or confined space concerns. Recommendations and/or remediation instructions are not a required part of this service. While some may be provided, they may not be detailed to cover all affected regulations & shall not be interpreted as such. Materials installed since the initial AHERA inspection may not be identified on this report. The materials are to be treated as suspect asbestos containing materials, & all applicable asbestos regulations are to be followed regarding these materials, regardless of installation date.

ACM = Asbestos Containing Material Non-ACM = Non-Asbestos Containing Material
 Damage Condition: ND=Not Damaged; D=Damaged; SD=Significantly Damaged Material Type: M=Miscellaneous; S=Surfacing; T=Thermal
 PLM = Polarized Light Microscopy TEM = Transmission Electron Microscopy N/A = Not Applicable



Asbestos Six-Month Periodic Surveillance

-- Building Materials Installed at Time of Initial Inspection

Peotone Elem. School
 426 N. Conrad Street
 Peotone, IL 60468
 School ID#: 56-099-207U-2003
 Peotone C.U.S.D. 207U

Surveillance Date: 4/8/2015
 Ideal Job Number: 18744

Mr. Gary Love, Maintenance Director
 Phone Number: 708-258-0991

Initial inspection of the building section(s) noted on this report has been conducted. Known & assumed asbestos containing materials installed at the time of initial inspection are noted below. This report also includes any subsequently installed materials that have been sampled & found to be asbestos containing or have been assumed to contain asbestos.

Area ID	Area Description	Area Location	Sampled & Analysis Type or Assumed	Material Type	Damage Condition	Friable	Response Action #	Change in Condition		See Notes
								Yes	No	
14	Boiler Room Ceiling (Roof Deck)	1959 Original Building Boiler Room	Sampled PLM	M	ND	No	N/A		X	
59MXA	Drywall Joint Compound	1959 Original Building Stage/Lofts, Storage Rooms & Corridor to Stage	Sampled PLM	M	ND	No	N/A		X	
No#	Base Cove	1959 Original Building & 1969 Addition Restrooms in Various Classrooms (some removed)	Assumed	M	ND	No	N/A		X	2
No#	Base Cove Mastic	1959 Original Building & 1969 Addition Restrooms in Various Classrooms (some removed)	Assumed	M	ND	No	N/A		X	2
No#	Black Tar Paper	1959 Original Building/1969/1971 Addition Tunnel System at 1959 Original Building Tunnel Entries	Assumed	M	ND	No	N/A		X	1
No#	Carpet Mastic	1959 Original Building Principal's Office & 1969 Addition Library & Rooms 128, 130 & 132	Assumed	M	ND	No	N/A		X	2
No#	Ceramic Tile Mastic	1959 Original Building & 1969 Addition in Corridors at Water Fountains	Assumed	M	ND	No	N/A		X	
No#	Ceramic Wall Tile Grout	1959 Original Building & 1969 Addition in Corridors at Water Fountains	Assumed	M	ND	No	N/A		X	

Surveyor: Steve Rock
 Surveyor #: 100-05617

Notes: 1) Accessed in limited area. It is assumed that no changes have taken place. 2) Area location has been updated. 3) Covered with linoleum. 4) Assumed to contain asbestos 4/8/2015. 5) Removed from kitchen storage 8/2014.

Areas removed & reported as such on prior reports are not listed on this report. Prior to any renovation/demolition, a specific inspection for localized and/or hidden suspect asbestos areas must be done, & this report is not a substitute for such an inspection. This report reflects information from the most current 3-year asbestos reinspection & subsequent 6-month surveillance reports. Changes in condition reflect observed changes since the last report only, not repairs and/or localized removal that may have been done previously. For changes in condition, "no" shall mean "none apparent". "Accessible" indicates materials, spaces or areas for which nothing is required to be removed to access the material, space, or area (i.e. no walls, ceilings, floors, outlet covers, etc. are required to be removed). "Inaccessible" indicates materials, spaces or areas for which something is required to be removed to access the material, space, or area. IDEAL reserves the right not to enter tunnels, crawlspaces, pipe chases or other area due to limited accessibility and/or confined space concerns. Recommendations and/or remediation instructions are not a required part of this service. While some may be provided, they may not be detailed to cover all affected regulations & shall not be interpreted as such. Materials installed since the initial AHERA inspection may not be identified on this report. The materials are to be treated as suspect asbestos containing materials, & all applicable asbestos regulations are to be followed regarding these materials, regardless of installation date.

ACM = Asbestos Containing Material Non-ACM = Non-Asbestos Containing Material
 Damage Condition: ND=Not Damaged; D=Damaged; SD=Significantly Damaged Material Type: M=Miscellaneous; S=Surfacing; T=Thermal
 PLM = Polarized Light Microscopy TEM = Transmission Electron Microscopy N/A = Not Applicable



Asbestos Six-Month Periodic Surveillance

-- Building Materials Installed at Time of Initial Inspection

Peotone Elem. School
 426 N. Conrad Street
 Peotone, IL 60468
 School ID#: 56-099-207U-2003
 Peotone C.U.S.D. 207U

Surveillance Date: 4/8/2015
 Ideal Job Number: 18744

Mr. Gary Love, Maintenance Director
 Phone Number: 708-258-0991

Initial inspection of the building section(s) noted on this report has been conducted. Known & assumed asbestos containing materials installed at the time of initial inspection are noted below. This report also includes any subsequently installed materials that have been sampled & found to be asbestos containing or have been assumed to contain asbestos.

Area ID	Area Description	Area Location	Sampled & Analysis Type or Assumed	Material Type	Damage Condition	Friable	Response Action #	Change in Condition		See Notes
								Yes	No	
No#	Fire Door	1959 Original Building Boiler Room	Assumed	M	ND	No	N/A		X	
No#	Floor Tile Mastic	1959 Original Building & 1969 Addition Throughout (some sampled, some removed)	Assumed	M	ND	No	N/A		X	
No#	Interior Boiler Materials	1959 Original Building Boiler Room	Assumed	M	ND	No	N/A		X	
No#	Interior Door Frame Caulk	1959 Original Building & 1969 Addition Various Areas	Assumed	M	ND	No	N/A		X	4
No#	Sheet Flooring	1959 Original Building & 1969 Addition Restrooms in Various Classrooms	Assumed	M	ND	No	N/A		X	2
No#	Sheet Flooring Mastic	1959 Original Building & 1969 Addition Restrooms in Various Classrooms	Assumed	M	ND	No	N/A		X	2
No#	Sink Undercoating	1959 Original Building Rooms 106, 108, 109, 111 & 113 & 1969 Addition Rooms 102-104, 128, 130 & 132	Assumed	M	ND	No	N/A		X	4
No#	Terrazzo Flooring	1959 Original Building Various Restrooms & 1969 Addition Hallways	Assumed	M	ND	No	N/A		X	

Surveyor: Steve Rock
 Surveyor #: 100-05617

Notes: **1) Accessed in limited area. It is assumed that no changes have taken place. 2) Area location has been updated. 3) Covered with linoleum. 4) Assumed to contain asbestos 4/8/2015. 5) Removed from kitchen storage 8/2014.**

Areas removed & reported as such on prior reports are not listed on this report. Prior to any renovation/demolition, a specific inspection for localized and/or hidden suspect asbestos areas must be done, & this report is not a substitute for such an inspection. This report reflects information from the most current 3-year asbestos reinspection & subsequent 6-month surveillance reports. Changes in condition reflect observed changes since the last report only, not repairs and/or localized removal that may have been done previously. For changes in condition, "no" shall mean "none apparent". "Accessible" indicates materials, spaces or areas for which nothing is required to be removed to access the material, space, or area (i.e. no walls, ceilings, floors, outlet covers, etc. are required to be removed). "Inaccessible" indicates materials, spaces or areas for which something is required to be removed to access the material, space, or area. IDEAL reserves the right not to enter tunnels, crawlspaces, pipe chases or other area due to limited accessibility and/or confined space concerns. Recommendations and/or remediation instructions are not a required part of this service. While some may be provided, they may not be detailed to cover all affected regulations & shall not be interpreted as such. Materials installed since the initial AHERA inspection may not be identified on this report. The materials are to be treated as suspect asbestos containing materials, & all applicable asbestos regulations are to be followed regarding these materials, regardless of installation date.

ACM = Asbestos Containing Material Non-ACM = Non-Asbestos Containing Material
 Damage Condition: ND=Not Damaged; D=Damaged; SD=Significantly Damaged Material Type: M=Miscellaneous; S=Surfacing; T=Thermal
 PLM = Polarized Light Microscopy TEM = Transmission Electron Microscopy N/A = Not Applicable